




JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
August 11, 2010

Reviewed: 

Mine Name: Travertine #1	Permit Number: M/023/0042
Operator Name: BEG Resources	Inspection Date: August 3, 2010
Inspector(s): Wayne Western	Time: 10:05 – 10:30 AM
Other Participants: None	Mine Status: Reclaimed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The Division on May 4, 2009 evaluated the site for vegetation. The Division found during the May 4, 2009 inspection that the vegetation met the 70% pre-mining cover standard. During the July 14, 2009 inspection, the Division found that the site was stable and that the road to and around the site was adequately maintained. The Division approved bond release.

Conclusions and Recommendations:

The Division retired the file. This was the final inspection of the site.

Directions:

1.6 miles north of Soma Quarry. Road to site is 0.1 miles south of mile marker 14. Site is approximately 0.6 miles from pavement. Go west on the road, which then turns east then south.

Inspector's Signature _____

WHW:vs

cc: Gary Burningham, Operator

Jerry Mansfield, BLM-Filmore

O:\M023-Juab\M0230042-Begtravertine\inspections\Ins_08032010.doc